

### FY2017 Dry Weather Screening Results - Sites with Detectable Flow (4 sites)

<i>Location of Sampling Site</i>	<i>Stormwater Structure ID</i>	<i>Conclusion</i>	<i>Remediation</i>
809 Virginia Avenue	MAN4300	Line was videoed by Public Works.	Referred to City Utilities.
642 Virginia Avenue	MAN4022	Line was videoed by Public Works.	Referred to City Utilities.
4008 Swannanoa	DI534	Did not find any pollutant sources. Flow determined to be from creek drainage backup.	Referred to City Drainage.
2504 Detroit Street	MAN3539	Flow is believed to be from crack in utilities pipe. Unable to locate source.	Referred to City Utilities.